



































Toyota group C








Inventory ID	Description	Unit Price	Quantity	Notes	Picture
#1	Nose mould		1		
#2	Tail mould ( broken)		1		
#3	Roof mould		1		
#4	Rear bumper (with electrics but need repair)		1		
#5	Rear wing with end plates		1		
#6	Driveshafts (4x new, 5x used)		9		
#7	Verious spec diffs (4 with CW, 3 without, 1 built)		7		








Inventory ID	Description	Unit Price	Quantity	Notes	Picture
#8	Main gearbox case (2 with pinion shaft and oil pick up, 1 with W/B mount, 2 without pinion shafts, 1 with oil pick up )		4		
#9	Gearbox casings (2 end casings, 2 mid)		4		
#10	Diff casing covers		5		
#11	Bell housing		1		
#12	CWP (8:31 complete set 15, 2x 9:31 pinions, 1x 9:31 CW, 1x 9:35 CW)		6		
#13	Gear Ratios ( see list)		149		
#14	Set of upright castings (2x fronts, 2x rears)		4		








Inventory ID	Description	Unit Price	Quantity	Notes	Picture
#15	Set of hubs (2x driveshaft flange, 6x wheel studs, 1x wheel nut)		13		
#16	Front drop link and 2x roll/sway bar blades, 4x roll /sway bar ends		5		
#17	3x headlight covers, 2x side windows (pair)		5		
#18	1 set of wheels		4		
#19	Various brake discs/rotors		7		
#20	LH rear rocker (rusty)		1		
#21	2x rear lights (1 missing lens) 1x rear light assembly		3		

Inventory ID	Description	Unit Price	Quantity	Notes	Picture
#22	Assorted rim parts (4x inside, 2x outside, old fittings)		7		
#23	Various alu pipes		6		
#24	Various carbon and aero parts		16		
#25	Wiper and mechanism		1		
#26	Turboc support mounts		3		
#27	2x front lower WB, 2x rear lower WB, RH rockers (NFG)		5		
#28	Exhaust manifold, 2x turbo (IHI, KKK)		3		

Inventory ID	Description	Unit Price	Quantity	Notes	Picture
#29	2x input shafts, 4x output flanges		6		
#30	Engine blocks		6		
#31	Cylinder heads (2x new, 4x used)		6		
#32	Intercooler		1		
#33	Water radiator		1		
#34	Crank shafts		4		
#35	Camshafts		8		

Inventory ID	Description	Unit Price	Quantity	Notes	Picture
#36	Engine oil pump		1		 A photograph of a single engine oil pump component lying on a grey surface. A small white label with the number "#36" is placed below the pump.
#37	Box of standard loom/electrics		1		 A photograph of an open cardboard box containing a bundle of various colored electrical wires and looms. A small white label with the number "#37" is placed below the box.
#38	Intake parts (damaged intake manifold, 4x ITB, 2x fuel rails, 16x injectors)		24		 A photograph showing a collection of engine intake components, including a manifold, fuel rails, and injectors, laid out on a grey surface. A small white label with the number "#38" is placed below the parts.
#39	Engine oil sump		1		 A photograph of a rectangular engine oil sump component lying on a grey surface. A small white label with the number "#39" is placed below the sump.
#40	Rocker cover (damaged)		1		 A photograph of a damaged rocker cover component lying on a grey surface. A small white label with the number "#40" is placed below the cover.
#41	Various engine pipes		7		 A photograph showing several different engine pipes and hoses laid out on a grey surface. A small white label with the number "#41" is placed below the pipes.
#42	Boxes of various engine parts		3		 A photograph showing three boxes containing various engine parts, including what appears to be a fuel rail and injectors, laid out on a grey surface. A small white label with the number "#42" is placed below the boxes.

Inventory ID	Description	Unit Price	Quantity	Notes	Picture
#43	Engine pulleys and brackets		13		
#44	Engine internals (rocker cover gasket, 3x boxes of bearings, head spacer and gasket, 6 front crank oil seals, 2x pulley bolts, 20x main journals, 8x used pistons, 4x used piston and con rods, 16x used con rods, 4x new pistons)		66		
#45	Set of used brake pads		1		
#46	Upright parts (bag of used bobbins, bag of new bobbins, 55x new drive pegs, 2x wheel bearing spaces, 4x hub washer)		63		
#47	various pulleys (4x main pulleys, 6x idle pulleys, 5x washers, 3x cam belt pulleys)		18		
#48	3x water pumps, 1x outlet		4		
#49	3x bags of various brackets		3		

Inventory ID	Description	Unit Price	Quantity	Notes	Picture
#50	fuel pump		1		
#51	Cam timing sensors		2		
#52	Various pipe work (5 bags)		5		
#53	Various bolts (5 bags)		5		
#54	Various seals (2x seals, 4x rings)		6		
#55	V-belt		1		
#56	Bearings		3		



Inventory ID	Description	Unit Price	Quantity	Notes	Picture
#57	Rad caps		3		
#58	Valves (5x intake, 5x exhaust)		10		
#59					

1x 19:30 2nd	1x 23:35 3rd	1x 27:29 top
4x 19:35 2nd	13x 23:32 4th	25x 27:29 5th
3x 20:27 3rd	3x 23:27 5th	7x 28:28 5th
1x 20:34 2nd	1x 23:26 5th	1x 29:28 top
2x 20:34 3rd	1x 24:32 top	2x 22:28 5th
1x 20:35 2nd	2x 24:32 4th	1x 27:29 4th
5x 20:35 3rd	1x 24:31 top	1x 22:28 top
8x 20:36 3rd	6x 24:31 5th	10x 27:28 5th
1x 21:35 3rd	1x 24:31 4th	2x 22:30 top
1x 22:36 3rd	1x 24:28 4th	3x 26:30 5th
1x 22:34 4th	4x 24:26 5th	9x 22:32 4th
2x 22:33 3rd	1x 25:30 4th	14x 26:29 5th
2x 22:33 4th	1x 25:31 4th	
1x 22:32 5th	4x 25:31 5th	